

10x0.1g



# AMW-PEN10

## Usage Tips:

- For best results, hang the scale from a steady location.
- If the mechanical indicator does not go to zero with no weight on the clip, you can correct it using the zero adjustment screw on the top of the scale.
- Do not leave weight hanging on the scale for extended periods of time.

